

CONDITION CHECK REPORT

No.	BH165915	CHASSIS No.	GH3-018398	DATE	2020 / 03 / 23
-----	----------	-------------	------------	------	----------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG				NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONE
5	TIRE (R FRONT)	OK	NG	195 / 65 R 15	RFT		17 A/C CONDITION	OK	NG		WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	OK	NG	195 / 65 R 15	RFT		18 INTERIOR CONDITION	OK	NG		DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	195 / 65 R 15	RFT		19 CHECK / WARNING LAMP	OK	E/G		ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	195 / 65 R 15	RFT		(COMMENT) INTERIOR: NG : OTHER SMELL 室内臭い					TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO	C D	DVD	SUN ROOF		FLIP DOWN MONITOR								
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)								
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。						

YARD	藤原A C 第3
------	----------

INSPECTER	aikawa
-----------	--------

AA SHEET	○
----------	---