

CR-V

CONDITION CHECK REPORT

車 No.	165825	CHASSIS No.	RM1-1101865	DATE	20 / 3 / 21
-------	--------	-------------	-------------	------	-------------

1	TIMING BELT CHANGE	<input checked="" type="radio"/> NO	YES		KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/> OK	NG			NONE	
2	COOLANT LEVEL	<input checked="" type="radio"/> OK	NG	LEAK			14	POWER WINDOW (L FRONT)	<input checked="" type="radio"/> OK	NG		NONE	
3	ENGINE OIL LEVEL	<input checked="" type="radio"/> OK	NG	DIRT			15	POWER WINDOW (R REAR)	<input checked="" type="radio"/> OK	NG		NONE	
4	OIL LEAKING	<input checked="" type="radio"/> OK	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	<input checked="" type="radio"/> OK	NG		NONE	
5	TIRE (R FRONT)	<input checked="" type="radio"/> OK	NG	225 65 R17	RFT		17	A/C CONDITION	<input checked="" type="radio"/> OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	<input checked="" type="radio"/> OK	NG	225 65 R17	RFT		18	INTERIOR CONDITION	<input checked="" type="radio"/> OK	NG	DIRT	SMOKING SMELL	<input checked="" type="radio"/> OTHER SMELL
7	TIRE (R REAR)	<input checked="" type="radio"/> OK	NG	225 65 R17	RFT		19	CHECK / WARNING LAMP	<input checked="" type="radio"/> OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	<input checked="" type="radio"/> OK	NG	225 65 R17	RFT		(COMMENT) 室内異臭有り(センター)					TESTER CHECK	
9	ENGINE NOISE	<input checked="" type="radio"/> OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	<input checked="" type="radio"/> OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	<input checked="" type="radio"/> OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT/MT)	<input checked="" type="radio"/> OK	NG	SHOCK	NOISE	SLIP							
OPTION													
<input checked="" type="radio"/> RADIO		<input checked="" type="radio"/> CD		<input checked="" type="radio"/> DVD		SUN ROOF		FLIP DOWN MONITOR					
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)					
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。 (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

火災

YARD 野田

INSPECTER K.S

AA SHEET 0