

E - Class

CONDITION CHECK REPORT

BF No. BH 165 744 CHASSIS No. WDD 2120592A 836077

DATE 20 201 3 1 24

1	TIMING BELT CHANGE	<u>NO</u>	YES		KM	13	POWER WINDOW (R FRONT)	<u>OK</u>	NG			NONE
2	COOLANT LEVEL	<u>OK</u>	NG	LEAK		14	POWER WINDOW (L FRONT)	<u>OK</u>	NG			NONE
3	ENGINE OIL LEVEL	<u>OK</u>	NG	DIRT		15	POWER WINDOW (R REAR)	<u>OK</u>	NG			NONE
4	OIL LEAKING	<u>OK</u>	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	<u>OK</u>	NG			NONE
5	TIRE (R FRONT)	<u>OK</u>	NG	<u>245 40 R 18</u>	RFT	17	A/C CONDITION	<u>OK</u>	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	<u>OK</u>	NG	<u>245 40 R</u>	RFT	18	INTERIOR CONDITION	<u>OK</u>	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	<u>OK</u>	NG	<u>265 35 R 18</u>	RFT	19	CHECK / WARNING LAMP	<u>OK</u>	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	<u>OK</u>	NG	<u>265 35 R 18</u>	RFT	(COMMENT)						TESTER CHECK
9	ENGINE NOISE	<u>OK</u>	NG	E/G	OTHERS							
10	ENGINE CONDITION	<u>OK</u>	NG	IDLING	SMOKE							
11	EXHAUST LEAK	<u>OK</u>	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT/MT)	<u>OK</u>	NG	SHOCK	NOISE							SLIP
OPTION												
<u>RADIO</u>	<u>CD</u>	<u>DVD</u>	SUN ROOF	FLIP DOWN MONITOR								
REAR MONITOR	<u>BACK CAMERA</u>	<u>CRUISE CONTROL</u>	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)								
POWER BACK DOOR												

(注意) オプション品が付いていて作動するのは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD USS ロジ野子田

INSPECTER KS

AA SHEET 0