

CONDITION CHECK REPORT

BF No.	BH168671	CHASSIS No.	ZAMCD39J000025342
--------	----------	-------------	-------------------

DATE ²⁰2017 / 3 / 24

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE
2	COOLANT LEVEL	OK	NG	LEAK	14	POWER WINDOW (L FRONT)	OK	NG		NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT	15	POWER WINDOW (R REAR)	OK	NG		NONE
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG	NONE
5	TIRE (R FRONT)	OK	NG	246/40 R19	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK CAN'T OPERATE A/C NONE
6	TIRE (L FRONT)	OK	NG	246/40 R19	RFT	18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL
7	TIRE (R REAR)	OK	NG	285/35 R19	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER
8	TIRE (L REAR)	OK	NG	285/35 R19	RFT	(COMMENT)				TESTER CHECK
9	ENGINE NOISE	OK	NG	E/G	OTHERS					
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE					
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS					
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE					
OPTION										
RADIO		CD		DVD		SUN ROOF		FLIP DOWN MONITOR		
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)		
POWER BACK DOOR										
<p>(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。</p> <p>(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。</p>										

YARD	博多箱崎
------	------

INSPECTER	みのる
-----------	-----

AA SHEET	○
----------	---