

CONDITION CHECK REPORT

BF No.	BH173763	CHASSIS No.	GK5-3003700	DATE	2020 / 3 / 30
--------	----------	-------------	-------------	------	---------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG				NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONE
5	TIRE (R FRONT)	OK	NG	185/60R15		RFT	17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE		NONE
6	TIRE (L FRONT)	OK	NG	185/60R15		RFT	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	185/60R15		RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	185/60R15		RFT	(COMMENT)				TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO		C D		DVD									
		BACK CAMERA		CRUISE CONTROL									
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	横浜(USロジ)	INSPECTER	平石	AA SHEET	✓
------	----------	-----------	----	----------	---