

# CONDITION CHECK REPORT

BH No.	176684	CHASSIS No.	NC26 - 024697
--------	--------	-------------	---------------

DATE **20.20** / **4** / **6**

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE	
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG			NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG			NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG			NONE	
5	TIRE (R FRONT)	OK	NG	195/65 R15		RFT	17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	OK	NG	/	R	RFT	18 INTERIOR CONDITION	OK	NG	RUST	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	/	R	RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	/	R	RFT	<p style="margin: 0;">(COMMENT)</p> <p style="font-size: 1.2em; margin: 5px 0;">タイヤ-レス!</p> <p style="font-size: 1.2em; margin: 5px 0;">A オートレス!</p> <p style="font-size: 1.2em; margin: 5px 0;">A 4WD!</p> <p style="font-size: 1.2em; margin: 5px 0;">タコメーターのノック。</p> <p style="font-size: 1.2em; margin: 5px 0;">カメラ</p> <p style="font-size: 1.2em; margin: 5px 0;">オートレス</p> <p style="font-size: 1.2em; margin: 5px 0;">オートレス</p>					TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR									
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR													
<p>(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。</p>													
<p>(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。</p>													

YARD	ECL木更津
------	--------

INSPECTER	由木
-----------	----

AA SHEET	0
----------	---