

CONDITION CHECK REPORT

BF No.	BH177789	CHASSIS No.	GRJ150-0002174	DATE	2020 / 4 / 1
--------	----------	-------------	----------------	------	--------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE
2	COOLANT LEVEL	OK	NG	LEAK			14	POWER WINDOW (L FRONT)	OK	NG			NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15	POWER WINDOW (R REAR)	OK	NG			NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	OK	NG			NONE
5	TIRE (R FRONT)	OK	NG	265/65R17	RFT		17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE
6	TIRE (L FRONT)	OK	NG	265/65R17	RFT		18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	265/65R17	RFT		19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	265/65R17	RFT		(COMMENT) LLC LEAK BOTH REAR TIRE FAILURE					TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO		C D		DVD		SUN ROOF							
		BACK CAMERA		CRUISE CONTROL									
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	名古屋(SPX上組 西五区)	INSPECTER	小林	AA SHEET	✓
------	----------------	-----------	----	----------	---