

CONDITION CHECK REPORT

BF No.	BH177574	CHASSIS No.	DE3FS-373050
--------	----------	-------------	--------------

DATE 2020 / 4 / 13

1	TIMING BELT CHANGE	YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG			NONE		
2	COOLANT LEVEL	(OK)	NG	LEAK		14	POWER WINDOW (L FRONT)	(OK)	NG		NONE		
3	ENGINE OIL LEVEL	(OK)	NG	DIRT		15	POWER WINDOW (R REAR)	(OK)	NG		NONE		
4	OIL LEAKING	(OK)	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	(OK)	NG		NONE		
5	TIRE (R FRONT)	(OK)	NG	175/65	R14	RFT	17	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	(OK)	NG	175/65	R14	RFT	18	INTERIOR CONDITION	(OK)	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	(OK)	NG	175/65	R14	RFT	19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	(OK)	NG	175/65	R14	RFT	(COMMENT)				TESTER CHECK		
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS								
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE								
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	(OK)	NG	SHOCK	NOISE	SLIP							
OPTION													
(RADIO)		(CD)		(DVD)		SUN ROOF		FLIP DOWN MONITOR					
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)					
POWER BACK DOOR													
<p>(注意) オプション品が付いていて作動するのは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。</p> <p>(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。</p>													

YARD	KANDA	INSPECTER	柳 詰	AA SHEET	○
------	-------	-----------	-----	----------	---