

# CONDITION CHECK REPORT

BF No.	BH178011	CHASSIS No.	TRH200-0037250
--------	----------	-------------	----------------

DATE     2020 / 3 / 31

No.	Item	Status	Leak	DIRT	SMALL	BIG	Tire	A/C	Interior	Warning Lamp	TESTER CHECK							
1	TIMING BELT CHANGE	YES									<div style="border: 1px solid black; padding: 5px;"> <p>(COMMENT)</p> <p style="text-align: right;">TESTER CHECK</p> </div>							
2	COOLANT LEVEL	NG	LEAK															
3	ENGINE OIL LEVEL	NG	DIRT															
4	OIL LEAKING	NG			SMALL	BIG												
5	TIRE (R FRONT)	NG					19580 R15 RFT	A/C CONDITION							WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	NG					19580 R15 RFT	INTERIOR CONDITION							DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	NG					19580 R15 RFT	CHECK / WARNING LAMP							E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	NG					19580 R15 RFT											
9	ENGINE NOISE	NG			E/G	OTHERS												
10	ENGINE CONDITION	NG			IDLING	SMOKE												
11	EXHAUST LEAK	NG			MUFFLER RUSTY	MISSING PARTS												
12	TRANSMISSION (AT / MT)	NG			SHOCK	NOISE	SLIP											
OPTION											<p>(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカ-で囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。</p>							
<input checked="" type="checkbox"/> RADIO	<input checked="" type="checkbox"/> CD	<input type="checkbox"/> DVD	<input type="checkbox"/> SUN ROOF	<input type="checkbox"/> FLIP DOWN MONITOR	<input type="checkbox"/> REAR MONITOR	<input type="checkbox"/> BACK CAMERA	<input type="checkbox"/> CRUISE CONTROL	<input type="checkbox"/> POWER SLIDING DOOR (LEFT)	<input type="checkbox"/> POWER SLIDING DOOR (RIGHT)	<input type="checkbox"/> POWER BACK DOOR								

YARD	KANDA	INSPECTER	柳 詰	AA SHEET	<input checked="" type="checkbox"/>
------	-------	-----------	-----	----------	-------------------------------------