

## CONDITION CHECK REPORT

---

BF No.	BH192473	CHASSIS No.	JN1SC2F24Z0855094			
1	CORROSION CONDITION (Less than)	0% 	25%	50%	75%	100%
2	Holes	NO 	YES			
3	Broken	NO 	YES			
4	Engine	OK 	NG			
5	Brake System	OK 	NG			
6	Heater	OK 	NG			
7	Power Window	OK 	NG			
8	Transmission	OK 	NG			
9	A/C	OK 	NG			
10	Audio System	OK 	NG			
11	4WD Working	OK	NG	NONE 		
<b>(Comment)</b> odometer light / screen need to repair						
UPDATE 2020/04/16 <span style="float: right;">ver 1.0</span>						