

CONDITION CHECK REPORT

BF No.	BH245630	CHASSIS No.	KMJRD37FP3K566093			
1	CORROSION CONDITION (Less than)	0%	25% 	50%	75%	100%
2	Holes	NO 	YES			
3	Broken	NO 	YES			
4	Engine	OK 	NG			
5	Brake System	OK 	NG			
6	Heater	OK 	NG			
7	Power Window	OK 	NG			
8	Transmission	OK 	NG			
9	A/C	OK 	NG			
10	Audio System	OK 	NG			
11	4WD Working	OK	NG	NONE 		
(Comment)						
UPDATE 2020/06/08						
ver 1.0						