

# CONDITION CHECK REPORT

2558 ミニヨン

BG No.	BH-254826	CHASSIS No.	FH218H-500119
--------	-----------	-------------	---------------

DATE 2020/6/16

1	TIMING BELT CHANGE	YES	NO	KM	13	POWER WINDOW (R FRONT)	OK	NG	NONE	
2	COOLANT LEVEL	OK	NG	LEAK	14	POWER WINDOW (L FRONT)	OK	NG	NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT	15	POWER WINDOW (R REAR)	OK	NG	NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG	NONE
5	TIRE (R FRONT)	OK	NG	7.50' - R16	RFT	17	A/C CONDITION	OK	NG	WIND FLOWS OK CAN'T OPERATE A/C NONE
6	TIRE (L FRONT)	OK	NG	7.50' - R16	RFT	18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL
7	TIRE (R REAR)	OK	NG	7.50' - R16	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER
8	TIRE (L REAR)	OK	NG	7.50' - R16	RFT	(COMMENT) 荷台 取扱リマ六 TESTER CHECK				
9	ENGINE NOISE	OK	NG	E/G	OTHERS					
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE					
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS					
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE					SLIP
OPTION										
RADIO		CD		DVD		SUN ROOF		FLIP DOWN MONITOR		
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)		
POWER BACK DOOR										
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いたします。 (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載お願いします。オプションシートをチェックして、U3・B3以上の傷みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。										

YARD	マツミ
------	-----

INSPECTER	吉野
-----------	----

AA SHEET	✓
----------	---