

# CONDITION CHECK REPORT

BF No.	BH342823	CHASSIS No.	BE63CE-300608
--------	----------	-------------	---------------

DATE 2020 / 7 / 9

1	TIMING BELT CHANGE	YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG			NONE						
2	COOLANT LEVEL	(OK)	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG		(NONE)						
3	ENGINE OIL LEVEL	(OK)	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG		(NONE)						
4	OIL LEAKING	(OK)	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG		(NONE)						
5	TIRE (R FRONT)	(OK)	NG	7.00	R16	RFT	17	A/C CONDITION	(OK)	NG	WIND BLOWS OK CAN'T OPERATE A/C NONE						
6	TIRE (L FRONT)	(OK)	NG	7.00	R16	RFT	18	INTERIOR CONDITION	(OK)	NG	DIRT SMOKING SMELL OTHER SMELL						
7	TIRE (R REAR)	(OK)	NG	7.00	R16	RFT	19	CHECK / WARNING LAMP	(OK)	E/G	ABS AIRBAG OTHER						
8	TIRE (L REAR)	(OK)	NG	7.00	R16	RFT	(COMMENT)				TESTER CHECK						
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS												
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE												
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS												
12	TRANSMISSION (AT / MT)	(OK)	NG	SHOCK	NOISE	SLIP											
OPTION																	
(RADIO)	(CD)	<del>DVD</del>	SUN ROOF	FLIP DOWN MONITOR													
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)													
POWER BACK DOOR																	

(注意) オプション品が付いていて作動するのは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD	KANDA	INSPECTER	柳 詰	AA SHEET	○
------	-------	-----------	-----	----------	---