

CONDITION CHECK REPORT

BH No.	363 8/2	CHASSIS No.	WDB2030921F844892
--------	---------	-------------	-------------------

DATE 2020 / 7 / 20

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE					
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG			NONE					
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG			NONE					
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG			NONE					
5	TIRE (R FRONT)	OK	NG	225 / 45 R 17		RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE				
6	TIRE (L FRONT)	OK	NG	↓	R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL				
7	TIRE (R REAR)	OK	NG	↓	R	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER				
8	TIRE (L REAR)	OK	NG	↓	R	RFT	<div style="font-size: 1.5em; font-weight: bold;">★ 車-UP!</div> <div style="font-size: 1.5em; font-weight: bold;">★ 107-30トク! 30トク!</div> <div style="font-size: 1.5em; font-weight: bold;">★ 107-1173527m 107!</div> <div style="font-size: 1.5em; font-weight: bold;">★ 720-7-</div> <div style="font-size: 1.5em; font-weight: bold;">★ 720-7-</div> <div style="font-size: 1.5em; font-weight: bold;">★ 720-7-</div>					TESTER CHECK					
9	ENGINE NOISE	OK	NG	E/G	OTHERS												
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE												
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS												
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP											
OPTION																	
RADIO	CD	DVD	SUN ROOF		FLIP DOWN MONITOR												
REAR MONITOR	BACK/CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)												
POWER BACK DOOR																	
<p>(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。</p>																	

YARD	ECL木更津
------	--------

INSPECTER	由小
-----------	----

AA SHEET	2
----------	---