

CONDITION CHECK REPORT

Hiace Van

BH No.	366053	CHASSIS No.	RZH112-7111622	DATE	2017/1/18
--------	--------	-------------	----------------	------	-----------

1	TIMING BELT CHANGE	(No)	YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG			NONE	
2	COOLANT LEVEL	(OK)	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	(NG)			NONE	
3	ENGINE OIL LEVEL	(OK)	NG	DIRT			15 POWER WINDOW (R REAR)	(OK)	NG			NONE	
4	OIL LEAKING	(OK)	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK'	NG			NONE	
5	TIRE (R FRONT)	(OK)	NG	195-80 R15 RFT			17 A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	(OK)	NG	195-80 R15 RFT			18 INTERIOR CONDITION	(OK)	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	(OK)	NG	245-50R14.5 RFT			19 CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	(OK)	NG	245-50 R14.5 RFT			(COMMENT) 左スタア=ササ 右QT1=ササ 右スタア=ササ カズトキス:K(⊕) 高土 222a 高土 478m					TESTER CHECK	
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS								
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE								
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT/MT)	(OK)	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO		C D		DVD		SUN ROOF		FLIP DOWN MONITOR					
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)					
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」でお願します。 (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやセビ(マーカで囲んで)、その他自立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	野田	INSPECTER	K.S	AA SHEET	0
------	----	-----------	-----	----------	---