

## CONDITION CHECK REPORT

No.	BH368484	CHASSIS No.	WDB211065-2A491666	DATE	2020 / 07 / 20
-----	----------	-------------	--------------------	------	----------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE	
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG				NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONE	
5	TIRE (R FRONT)	OK	NG	225 / 55 R 16	RFT		17 A/C CONDITION	OK	NG		WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	OK	NG	225 / 55 R 16	RFT		18 INTERIOR CONDITION	OK	NG		DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	225 / 55 R 16	RFT		19 CHECK / WARNING LAMP	OK	E/G		ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	225 / 55 R 16	RFT		(COMMENT) OIL LEAKING: NG : SMALL  オイルしみ (ボディ) 右ミラー電格不良。 ハンドルスレ。 シートしわ。 ディスク読み込まない。					TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS									
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE									
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP								
OPTION														
RADIO	<del>CD</del>	<del>DVD</del>	SUN ROOF	FLIP DOWN MONITOR										
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)										
POWER BACK DOOR														
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、 オプション品が付いていないものは「無印」でお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで 囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。							

YARD	藤原AC第3
------	--------

INSPECTER	fudano
-----------	--------

AA SHEET	○
----------	---