

CONDITION CHECK REPORT

3699 #27-

BH No	370998	CHASSIS No.	FE52EB-450 106
-------	--------	-------------	----------------

DATE 2020/7/27

1	TIMING BELT CHANGE	YES	NG	LEAK	DIRT	SMALL	BIG	13	POWER WINDOW (R FRONT)	OK	NG	NONE
2	COOLANT LEVEL	OK	NG					14	POWER WINDOW (L FRONT)	OK	NG	NONE
3	ENGINE OIL LEVEL	OK	NG					15	POWER WINDOW (R REAR)	OK	NG	NONE
4	OIL LEAKING	OK	NG					16	POWER WINDOW (L REAR)	OK	NG	NONE
5	TIRE (R FRONT)	OK	NG	205/70 R16	RFT			17	A/C CONDITION	OK	NG	WIND BLOWS OK CAN'T OPERATE A/C NONE
6	TIRE (L FRONT)	OK	NG	205/70 R16	RFT			18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL
7	TIRE (R REAR)	OK	NG	205/70 R16	RFT			19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER
8	TIRE (L REAR)	OK	NG	205/70 R16	RFT			(COMMENT) 左FRタイヤ スタッドレス ショッキ 欠品				TESTER CHECK
9	ENGINE NOISE	OK	NG	E/G	OTHERS							
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP						
OPTION												
	RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR							
	REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)							
	POWER BACK DOOR											
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いたします。 (注意) NGが入った項目は、窓ガラスに貼付せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の傷みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。												

YARD	マツミ
------	-----

INSPECTER	谷田
-----------	----

AA SHEET	✓
----------	---