

CONDITION CHECK REPORT

BH No.	37/030	CHASSIS No.	SK F2V-2035 93
--------	--------	-------------	----------------

DATE 20.20 / 7 25

1	TIMING BELT CHANGE		YES			KM	13	POWER WINDOW (R FRONT)	NG			NONE		
2	COOLANT LEVEL	OK	NG	LEAK			14	POWER WINDOW (L FRONT)	NG			NONE		
3	ENGINE OIL LEVEL	OK	NG	DIRT			15	POWER WINDOW (R REAR)	OK			NONE		
4	OIL LEAKING	OK	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	OK			NONE		
5	TIRE (R FRONT)	OK	NG	175/27 R/4		RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	OK	NG	/ R		RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	175/27 R/2		RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	/ R		RFT	(COMMENT) #175 #175						TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS									
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE									
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK	NOISE	SLIP								
OPTION														
	RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR									
	REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)									
	POWER BACK DOOR													
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。	

YARD	ECL木更津
------	--------

INSPECTER	[Signature]
-----------	-------------

AA SHEET	9
----------	---