

CONDITION CHECK REPORT

BF No.	B4369372	CHASSIS No.	E11-701018
--------	----------	-------------	------------

DATE 2020 / 7 / 22

No.	Item	Status		Leak / Dirt			Item	Status	Other				
		OK	NG	SMALL	BIG	DIRT			Item	Status	WIND BLOWS OK	SMOKING SMELL	OTHER SMELL
1	TIMING BELT CHANGE		YES				13	POWER WINDOW (R FRONT)	OK	NG			NONE
2	COOLANT LEVEL	OK	NG	LEAK			14	POWER WINDOW (L FRONT)	OK	NG			NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15	POWER WINDOW (R REAR)	OK	NG			NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	OK	NG			NONE
5	TIRE (R FRONT)	OK	NG	175/65 R14	RFT		17	AIR CONDITION	OK	NG	WIND BLOWS OK		NONE
6	TIRE (L FRONT)	OK	NG	175/65 R14	RFT		18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	175/65 R14	RFT		19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	175/65 R14	RFT		(COMMENT) <div style="font-size: 1.2em; margin-top: 20px;">左Fタスペーキング</div>						
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO	G.D.	DVD	SUN ROOF	FLIP DOWN MONITOR									
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR													

(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

Yard		Inspector	子
			AA SHEET 0