

C-Class

CONDITION CHECK REPORT

BF No.	373301	CHASSIS No.	WDD2040541A402739	DATE	20 17 22
--------	--------	-------------	-------------------	------	----------

1	TIMING BELT CHANGE	<input checked="" type="radio"/> NO	YES		KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/> OK	NG			NONE
2	COOLANT LEVEL	<input checked="" type="radio"/> OK	NG	LEAK		14	POWER WINDOW (L FRONT)	<input checked="" type="radio"/> OK	NG			NONE
3	ENGINE OIL LEVEL	<input checked="" type="radio"/> OK	NG	DIRT		15	POWER WINDOW (R REAR)	<input checked="" type="radio"/> OK	NG			NONE
4	OIL LEAKING	<input checked="" type="radio"/> OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	<input checked="" type="radio"/> OK	NG			NONE
5	TIRE (R FRONT)	<input checked="" type="radio"/> OK	NG	225 45 R 17	RFT	17	A/C CONDITION	<input checked="" type="radio"/> OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	<input checked="" type="radio"/> OK	NG	225 45 R 17	RFT	18	INTERIOR CONDITION	<input checked="" type="radio"/> OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	<input checked="" type="radio"/> OK	NG	225 45 R 17	RFT	19	CHECK / WARNING LAMP	<input checked="" type="radio"/> OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	<input checked="" type="radio"/> OK	NG	225 45 R 17	RFT	(COMMENT)						TESTER CHECK
9	ENGINE NOISE	<input checked="" type="radio"/> OK	NG	E/G	OTHERS							NOISE
10	ENGINE CONDITION	<input checked="" type="radio"/> OK	NG	IDLING	SMOKE							1.7L
11	EXHAUST LEAK	<input checked="" type="radio"/> OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT / MT)	<input checked="" type="radio"/> OK	NG	SHOCK	NOISE							SLIP
OPTION		<input checked="" type="radio"/> RADIO	<input checked="" type="radio"/> CD	<input checked="" type="radio"/> DVD	SUN ROOF	FLIP DOWN MONITOR						
REAR MONITOR	BACK CAMERA	<input checked="" type="radio"/> CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)								
POWER BACK DOOR												
<p>(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。</p>							<p>(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。</p>					

YARD	USS 口シ野田
------	----------

INSPECTER	KS
-----------	----

AA SHEET	<input checked="" type="radio"/>
----------	----------------------------------