

# CONDITION CHECK REPORT

BH No.	379996	CHASSIS No.	ACU30-0075445
--------	--------	-------------	---------------

DATE **2020 / 7 / 31**

1	TIMING BELT CHANGE		YES			KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE
2	COOLANT LEVEL	OK	NG	LEAK			14	POWER WINDOW (L FRONT)	OK	NG			NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15	POWER WINDOW (R REAR)	OK	NG			NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	OK	NG			NONE
5	TIRE (R FRONT)	OK	NG	265 / 35 R 22		RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	OK	NG	/	R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	/	R	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	↓	R	RFT	<div style="border: 1px solid black; padding: 5px;"> <p style="margin: 0;">(COMMENT)</p> <p style="font-size: 1.2em; margin: 5px 0;">* 27/273- (特修)</p> <p style="font-size: 1.2em; margin: 5px 0;">* 27/273- (特修)</p> <p style="font-size: 1.2em; margin: 5px 0;">* 27/273- (特修)</p> <p style="font-size: 1.2em; margin: 5px 0;">* 27/273- (特修)</p> </div> <div style="text-align: right; margin-top: 10px;"> <p style="font-size: 1.2em;">* 27/273- (特修)</p> <p style="font-size: 1.2em;">* 27/273- (特修)</p> <p style="font-size: 1.2em;">* 27/273- (特修)</p> </div>						
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (A / MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO	C D	DVD	SUN ROOF	FLIP DOWN MONITOR									
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。						

YARD	ECL木更津
------	--------

INSPECTER	[Signature]
-----------	-------------

AA SHEET	2
----------	---