

19/52

E-Class

CONDITION CHECK REPORT

BH No.	379 813	CHASSIS No.	WDB2110561A750355	DATE	2017/127
--------	---------	-------------	-------------------	------	----------

1	TIMING BELT CHANGE	<input checked="" type="radio"/> NO	YES			13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/> OK	NG			NONE
2	COOLANT LEVEL	<input checked="" type="radio"/> OK	NG	LEAK		14	POWER WINDOW (L FRONT)	<input checked="" type="radio"/> OK	NG			NONE
3	ENGINE OIL LEVEL	<input checked="" type="radio"/> OK	NG	DIRT		15	POWER WINDOW (R REAR)	<input checked="" type="radio"/> OK	NG			NONE
4	OIL LEAKING	<input checked="" type="radio"/> OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	<input checked="" type="radio"/> OK	NG			NONE
5	TIRE (R FRONT)	<input checked="" type="radio"/> OK	NG	245 40 R18	RFT	17	A/C CONDITION	<input checked="" type="radio"/> OK	<input checked="" type="radio"/> NG	<input checked="" type="radio"/> CAN'T OPERATE		A/C NONE
6	TIRE (L FRONT)	<input checked="" type="radio"/> OK	NG	245 40 R18	RFT	18	INTERIOR CONDITION	<input checked="" type="radio"/> OK	NG	<input checked="" type="radio"/> DIRT	<input checked="" type="radio"/> SMOKING SMELL	<input checked="" type="radio"/> OTHER SMELL
7	TIRE (R REAR)	<input checked="" type="radio"/> OK	NG	265 35 R18	RFT	19	CHECK / WARNING LAMP	<input checked="" type="radio"/> OK	E/G	<input checked="" type="radio"/> ABS	<input checked="" type="radio"/> AIRBAG	<input checked="" type="radio"/> OTHER
8	TIRE (L REAR)	<input checked="" type="radio"/> OK	NG	265 35 R18	RFT	(COMMENT) フード"開かず" クリル破損 A/C 冷えず (17"を引ける様には多量要) 灯不良			TESTER CHECK			
9	ENGINE NOISE	<input checked="" type="radio"/> OK	NG	E/G	OTHERS							
10	ENGINE CONDITION	<input checked="" type="radio"/> OK	NG	IDLING	SMOKE							
11	EXHAUST LEAK	<input checked="" type="radio"/> OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT/MT)	<input checked="" type="radio"/> OK	NG	SHOCK	NOISE				SLIP			

OPTION				
<input checked="" type="radio"/> RADIO	<input checked="" type="radio"/> CD	<input checked="" type="radio"/> DVD	<input type="radio"/> SUN ROOF	<input type="radio"/> FLIP DOWN MONITOR
<input type="radio"/> REAR MONITOR	<input type="radio"/> BACK CAMERA	<input checked="" type="radio"/> CRUISE CONTROL	<input type="radio"/> POWER SLIDING DOOR (LEFT)	<input type="radio"/> POWER SLIDING DOOR (RIGHT)
<input type="radio"/> POWER BACK DOOR				

(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」でお願います。

(注意) NGが入った項目は、窓ガラスに貼付せずコメントにすべて記載をお願いします。オーゲメントシートをチェックして、U8-B3以上の西みキズ、フロントガラスの割れやヒビ(マーカで隠して)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD	野田
------	----

INSPECTER	KS
-----------	----

AA SHEET	0
----------	---