

CONDITION CHECK REPORT

BF No.	BH381604	CHASSIS No.	RG1-1348993	DATE	2020 / 7 / 29
--------	----------	-------------	-------------	------	---------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE	
2	COOLANT LEVEL	OK	NG	LEAK			14	POWER WINDOW (L FRONT)	OK	NG			NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT			15	POWER WINDOW (R REAR)	OK	NG			NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	OK	NG			NONE	
5	TIRE (R FRONT)	OK	NG	205/60R16	RFT		17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE	
6	TIRE (L FRONT)	OK	NG	205/60R16	RFT		18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	205/60R16	RFT		19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	205/60R16	RFT		(COMMENT) OIL LEAKING SMALL DVD FAILURE					TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS									
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE									
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP								
OPTION														
RADIO		C D		DVD										
		BACK CAMERA		POWER SLIDING DOOR(LEFT)		POWER SLIDING DOOR(RIGHT)								
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。														
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。														

YARD	長州出島(リアル下関海陸)	INSPECTER	大城	AA SHEET	✓
------	---------------	-----------	----	----------	---