

# CONDITION CHECK REPORT

BF No.	BH382490	CHASSIS No.	ACU30-0021698	DATE	2020 / 7 / 31
--------	----------	-------------	---------------	------	---------------

No.	Item	YES	NG	LEAK	DIRT	SMALL	BIG	RFT	LFT	Item	OK	NG	E/G	ABS	AIRBAG	OTHER	
1	TIMING BELT CHANGE									13 POWER WINDOW (R FRONT)	OK	NG				NONE	
2	COOLANT LEVEL			LEAK						14 POWER WINDOW (L FRONT)	OK	NG				NONE	
3	ENGINE OIL LEVEL				DIRT					15 POWER WINDOW (R REAR)	OK	NG				NONE	
4	OIL LEAKING					SMALL	BIG			16 POWER WINDOW (L REAR)	OK	NG				NONE	
5	TIRE (R FRONT)							255/35 R20	RFT	17 A/C CONDITION	OK	NG		WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)							255/35 R20	RFT	18 INTERIOR CONDITION	OK	NG		DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)							255/35 R20	RFT	19 CHECK / WARNING LAMP	OK	NG	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)							255/35 R20	RFT	(COMMENT)  大"ニ"ネ"ト"ト"=1R-TR良     (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで 囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。							
9	ENGINE NOISE				E/G	OTHERS										TESTER CHECK	
10	ENGINE CONDITION				IDLING	SMOKE											
11	EXHAUST LEAK				MUFFLER RUSTY	MISSING PARTS											
12	TRANSMISSION (AT / MT)				SHOCK	NOISE	SLIP										
OPTION																	
RADIO		CD		DVD		SUN ROOF		FLIP DOWN MONITOR									
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR																	

YARD	KANDA	INSPECTER	柳 詰	AA SHEET	0
------	-------	-----------	-----	----------	---