

CONDITION CHECK REPORT

Harrier

Bg No.	393729	CHASSIS No.	ACV35-0011413	DATE	20/8/1
--------	--------	-------------	---------------	------	--------

1	TIMING BELT CHANGE	(NO)	YES		13	POWER WINDOW (R FRONT)	(OK)	NG			NONE	
2	COOLANT LEVEL	(OK)	NG	LEAK	14	POWER WINDOW (L FRONT)	(OK)	NG			NONE	
3	ENGINE OIL LEVEL	(OK)	NG	DIRT	15	POWER WINDOW (R REAR)	(OK)	NG			NONE	
4	OIL LEAKING	(OK)	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	(OK)	NG		NONE	
5	TIRE (R FRONT)	(OK)	NG	235/55 R18	RFT	17	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	(OK)	NG	235/55 R18	RFT	18	INTERIOR CONDITION	(OK)	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	(OK)	NG	235/55 R18	RFT	19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	(OK)	NG	235/55 R18	RFT	(COMMENT) ドボートワレ (大)					TESTER CHECK	
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS							
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE							
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT/MT)	(OK)	NG	SHOCK	NOISE						SLIP	
OPTION												
RADIO		CD		DVD		SUN ROOF		FLIP DOWN MONITOR				
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)				
POWER BACK DOOR												
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」で記載します。												
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オプションシートをチェックして、U3-B3以上の傷みキズ、フロントガラスの割れやヒビ(マーカで隠んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。												

YARD	野田	INSPECTER	KS	AA SHEET	○
------	----	-----------	----	----------	---