

# CONDITION CHECK REPORT

March

B# No.	440 491	CHASSIS No.	K13-704201
--------	---------	-------------	------------

DATE 2018/8/29

1	TIMING BELT CHANGE	(NG)	YES		K13	POWER WINDOW (R FRONT)	(OK)	NG			NONE	
2	COOLANT LEVEL	(OK)	NG	LEAK		POWER WINDOW (L FRONT)	(OK)	NG			NONE	
3	ENGINE OIL LEVEL	(OK)	NG	DIRT		POWER WINDOW (R REAR)	(OK)	NG			NONE	
4	OIL LEAKING	(OK)	NG	SMALL	BIG	POWER WINDOW (L REAR)	(OK)	NG			NONE	
5	TIRE (R FRONT)	(OK)	NG	165 70 R14	RFT	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	(OK)	NG	165 70 R14	RFT	INTERIOR CONDITION	(OK)	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	(OK)	NG	165 70 R14	RFT	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	(OK)	NG	165 70 R14	RFT	(COMMENT) 左前QT 12点 (大) 右RTP 12点 左70R14-12点 72"					TESTER CHECK	
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS							
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE							
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT/MT)	(OK)	NG	SHOCK	NOISE						SLIP	

OPTION <i>DVD 付</i>				
RADIO	CD	<del>DVD</del>	SUN ROOF	FLIP DOWN MONITOR
REAR MONITOR	BACK CAMERA	<del>CRUISE CONTROL</del>	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)
POWER BACK DOOR				

(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」でお記します。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オプションシートをチェックして、U3-B3以上の四みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD	野田
------	----

INSPECTER	K.S
-----------	-----

AA SHEET	0
----------	---