

Harrier

CONDITION CHECK REPORT

BH No.	440523	CHASSIS No.	ACU30-0080624	DATE	20 / 8 / 29
--------	--------	-------------	---------------	------	-------------

1	TIMING BELT CHANGE	(NO)	YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG			NONE	
2	COOLANT LEVEL	(OK)	NG	LEAK			14	POWER WINDOW (L FRONT)	(OK)	NG		NONE	
3	ENGINE OIL LEVEL	(OK)	NG	DIRT			15	POWER WINDOW (R REAR)	(OK)	NG		NONE	
4	OIL LEAKING	(OK)	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	(OK)	NG		NONE	
5	TIRE (R FRONT)	(OK)	NG	225/65 R17	RFT		17	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	(OK)	NG	225/65 R17	RFT		18	INTERIOR CONDITION	(OK)	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	(OK)	NG	225/65 R17	RFT		19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	(OK)	NG	225/65 R17	RFT		(COMMENT) ドポート 7V (1) ハーフキ					TESTER CHECK	
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS								
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE								
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	(OK)	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO		CD		DVD		SUN ROOF		FLIP DOWN MONITOR					
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)					
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」で記載します。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オプションシートを添付して、U9-B3以上の固みキズ、フロントガラスの割れやヒビ(マーカで隠して)、その他目立つ破損部分があった場合は、写真撮影をお願いします。						

YARD	野田
------	----

INSPECTER	K.S
-----------	-----

AA SHEET	0
----------	---