

Swift

CONDITION CHECK REPORT

BH No.	440 441	CHASSIS No.	ZC72S-310432
--------	---------	-------------	--------------

DATE 20 / 8 / 29

1	TIMING BELT CHANGE	(NO)	YES			13	POWER WINDOW (R FRONT)	(OK)	NG			NONE
2	COOLANT LEVEL	(OK)	NG	LEAK		14	POWER WINDOW (L FRONT)	(OK)	NG			NONE
3	ENGINE OIL LEVEL	(OK)	NG	DIRT		15	POWER WINDOW (R REAR)	(OK)	NG			NONE
4	OIL LEAKING	(OK)	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	(OK)	NG			NONE
5	TIRE (R FRONT)	(OK)	NG	185-55 R 16	RFT	17	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	(OK)	NG	185-55 R 16	RFT	18	INTERIOR CONDITION	(OK)	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	(OK)	NG	185-55 R 16	RFT	19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	(OK)	NG	185-55 R 16	RFT	(COMMENT)						TESTER CHECK
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS							
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE							
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT / MT)	(OK)	NG	SHOCK	NOISE							SLIP
OPTION												
RADIO		SD		DVD		SUN ROOF		FLIP DOWN MONITOR				
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)				
POWER BACK DOOR												
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」でお願します。						(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オーグメントシートをチェックして、U9-B3以上の窓みキズ、フロントガラスの割れやヒビ(マーカで隠して)、その他目立つ破損部分があった場合は、写真撮影をお願いします。						

YARD	野田
------	----

INSPECTER	K.S
-----------	-----

AA SHEET	0
----------	---