

# CONDITION CHECK REPORT

BF No.	BH452985	CHASSIS No.	NZE141-6160223	DATE	2020 / 9 / 5
--------	----------	-------------	----------------	------	--------------

1	TIMING BELT CHANGE		YES				KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/> OK	NG			NONE
2	COOLANT LEVEL	<input checked="" type="radio"/> OK	NG	LEAK				14	POWER WINDOW (L FRONT)	<input checked="" type="radio"/> OK	NG			NONE
3	ENGINE OIL LEVEL	<input checked="" type="radio"/> OK	NG	DIRT				15	POWER WINDOW (R REAR)	<input checked="" type="radio"/> OK	NG			NONE
4	OIL LEAKING	<input checked="" type="radio"/> OK	NG	SMALL	BIG			16	POWER WINDOW (L REAR)	<input checked="" type="radio"/> OK	NG			NONE
5	TIRE (R FRONT)	<input checked="" type="radio"/> OK	NG	185/70R14		RFT		17	A/C CONDITION	<input checked="" type="radio"/> OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE
6	TIRE (L FRONT)	<input checked="" type="radio"/> OK	NG	185/70R14		RFT		18	INTERIOR CONDITION	<input checked="" type="radio"/> OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	<input checked="" type="radio"/> OK	NG	185/70R14		RFT		19	CHECK / WARNING LAMP	<input checked="" type="radio"/> OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	<input checked="" type="radio"/> OK	NG	185/70R14		RFT		(COMMENT) RADIO & CD FAILURE				TESTER CHECK		
9	ENGINE NOISE	<input checked="" type="radio"/> OK	NG	E/G	OTHERS									
10	ENGINE CONDITION	<input checked="" type="radio"/> OK	NG	IDLING	SMOKE									
11	EXHAUST LEAK	<input checked="" type="radio"/> OK	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION ( <input checked="" type="radio"/> AT / MT)	<input checked="" type="radio"/> OK	NG	SHOCK	NOISE	SLIP								
OPTION														
<input checked="" type="radio"/> RADIO		<input checked="" type="radio"/> CD												
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。														
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。														

YARD	名古屋(SPX上組 西五区)	INSPECTER	小林	AA SHEET	✓
------	----------------	-----------	----	----------	---