

CONDITION CHECK REPORT

BF No.	BH453136	CHASSIS No.	JWE25-182993
--------	----------	-------------	--------------

DATE 2020 / 9 / 7

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG			NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG			NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG			NONE
5	TIRE (R FRONT)	OK	NG	185/80 R/15		RFT	17 AIR CONDITION	OK	NG	WIND BLOWS OK		NONE
6	TIRE (L FRONT)	OK	NG	185/80 R/15		RFT	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	185/80 R/15		RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	185/80 R/15		RFT	(COMMENT)					
9	ENGINE NOISE	OK	NG	E/G	OTHERS							
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK	NOISE	SLIP						
OPTION												
	RADIO	C D	DVD	SUN ROOF	FLIP DOWN MONITOR							
	REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)							
	POWER BACK DOOR											
							<p>(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで困んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。</p>					

Yard	
------	--

Inspector	7 5
-----------	-----

AA SHEET	9
----------	---