

H250 NO.8 727-REV

CONDITION CHECK REPORT

BH NO. BG455797 CHASSIS No. FE70CB504534

DATE 2020/2/17

1	TIMING BELT CHANGE		YES		13	POWER WINDOW (R FRONT)	OK	NG			NONE															
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG		NONE															
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG		NONE															
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG		NONE															
5	TIRE (R FRONT)	OK	NG	205/65 R16	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE														
6	TIRE (L FRONT)	OK	NG	205/65 R16	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL														
7	TIRE (R REAR)	OK	NG	205/65 R16	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER														
8	TIRE (L REAR)	OK	NG	205/65 R16	RFT	(COMMENT) ・ AC不良. 冷えず ・ 右PW不良 ・ ミートキ ・ 左右アルミドア開かず (注意) NGが入った項目は、窓ガラスに貼るせずコメントにすべて記載をお願いします。 オークションシートをチェックして、U8-B3以上の傷みキズ、フロントガラスの割れやヒビ(マーカで隠す)、その他目立つ破損部分があった場合は、写真撮影をお願いします。																				
9	ENGINE NOISE	OK	NG	E/G	OTHERS																					
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE																					
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS																					
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE							SLIP														
OPTION <table border="1"> <tr> <td>RADIO</td> <td>CD</td> <td>DVD</td> <td>SUN ROOF</td> <td>FLIP DOWN MONITOR</td> </tr> <tr> <td>REAR MONITOR</td> <td>BACK CAMERA</td> <td>CRUISE CONTROL</td> <td>POWER SLIDING DOOR (LEFT)</td> <td>POWER SLIDING DOOR (RIGHT)</td> </tr> <tr> <td>POWER BACK DOOR</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>												RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR	REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)	POWER BACK DOOR				
RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR																						
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)																						
POWER BACK DOOR																										

YARD マツミ

INSPECTOR 727

AA SHEET