

CONDITION CHECK REPORT

| | | | |
|--------|-----------------|-------------|-------------|
| BF No. | BH458453 | CHASSIS No. | NCEC-102960 |
|--------|-----------------|-------------|-------------|

DATE 2020 / 12 / 7

| | | | | | | | | | | | | | |
|---|----------------------|----------------|---------------------------|----------------------------|---------------|------|--|------------------------|----|-----|---------------|---------------|-------------|
| 1 | TIMING BELT CHANGE | | YES | | KM | 13 | POWER WINDOW (R FRONT) | OK | NG | | | NONE | |
| 2 | COOLANT LEVEL | OK | NG | LEAK | | | 14 | POWER WINDOW (L FRONT) | OK | NG | | NONE | |
| 3 | ENGINE OIL LEVEL | OK | NG | DIRT | | | 15 | POWER WINDOW (R REAR) | OK | NG | | NONE | |
| 4 | OIL LEAKING | OK | NG | SMALL | BIG | | 16 | POWER WINDOW (L REAR) | OK | NG | | NONE | |
| 5 | TIRE (R FRONT) | OK | NG | 205/50 R 16 | RFT | | 17 | A/C CONDITION | OK | NG | WIND BLOWS OK | CAN'T OPERATE | A/C NONE |
| 6 | TIRE (L FRONT) | OK | NG | 205/50 R 16 | RFT | | 18 | INTERIOR CONDITION | OK | NG | DIRT | SMOKING SMELL | OTHER SMELL |
| 7 | TIRE (R REAR) | OK | NG | 205/50 R 16 | RFT | | 19 | CHECK / WARNING LAMP | OK | E/G | ABS | AIRBAG | OTHER |
| 8 | TIRE (L REAR) | OK | NG | 205/50 R 16 | RFT | | (COMMENT) ミートス、ハブ 室内、ヨコシ スパリア他ス車 幌破れ | | | | | TESTER CHECK | |
| 9 | ENGINE NOISE | OK | NG | E/G | OTHERS | | | | | | | | |
| 10 | ENGINE CONDITION | OK | NG | IDLING | SMOKE | | | | | | | | |
| 11 | EXHAUST LEAK | OK | NG | MUFFLER RUSTY | MISSING PARTS | | | | | | | | |
| 12 | TRANSMISSION (AT/MT) | OK | NG | SHOCK | NOISE | SLIP | | | | | | | |
| OPTION | | | | | | | | | | | | | |
| RADIO | CD | DVD | SUN ROOF | FLIP DOWN MONITOR | | | | | | | | | |
| REAR MONITOR | BACK CAMERA | CRUISE CONTROL | POWER SLIDING DOOR (LEFT) | POWER SLIDING DOOR (RIGHT) | | | | | | | | | |
| POWER BACK DOOR | | | | | | | | | | | | | |
| (注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。 | | | | | | | | | | | | | |
| (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ（マーカで囲んで）、その他目立つ破損部分があった場合は、写真撮影をお願いします。 | | | | | | | | | | | | | |

| | |
|------|------------|
| YARD | ナガセ自動車株式会社 |
|------|------------|

| | |
|-----------|------|
| INSPECTER | 尾銅竜也 |
|-----------|------|

| |
|----------|
| AA SHEET |
|----------|