

## CONDITION CHECK REPORT

---

BF No.	BH462478	CHASSIS No.	VSK99030			
1	CORROSION CONDITION (Less than)	0%	25% 	50%	75%	100%
2	Holes	NO 	YES			
3	Broken	NO 	YES			
4	Engine	OK 	NG			
5	Brake System	OK 	NG			
6	Heater	OK 	NG			
7	Power Window	OK 	NG			
8	Transmission	OK 	NG			
9	A/C	OK 	NG			
10	Audio System	OK 	NG			
11	4WD Working	OK 	NG	NONE		
<b>(Comment)</b> THERE IS NO GUARANTEE ABOUT HOLES AND BROKEN  SOLD AS IS & SHOWN						
UPDATE 2020/09/09 <span style="float: right;">ver 1.0</span>						