

CONDITION CHECK REPORT

BF No. <u>B1-1469972</u>	CHASSIS No. <u>NCPS1-0142504</u>	DATE <u>2020 / 9 / 15</u>
--------------------------	----------------------------------	---------------------------

1	TIMING BELT CHANGE	YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG			NONE		
2	COOLANT LEVEL	(OK)	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG		(NONE)		
3	ENGINE OIL LEVEL	(OK)	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG		(NONE)		
4	OIL LEAKING	(OK)	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG		(NONE)		
5	TIRE (R FRONT)	(OK)	NG	165	R13	RFT	17	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	(OK)	NG	165	R13	RFT	18	INTERIOR CONDITION	OK	(NG)	(DIRT)	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	(OK)	NG	165	R13	RFT	19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	(OK)	NG	165	R13	RFT	(COMMENT)					TESTER CHECK	
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS								
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE								
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT/ MT)	(OK)	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR									
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR													
<p>(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。</p> <p>(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。</p>													

YARD	KANDA	INSPECTER	柳詰	AA SHEET
------	-------	-----------	----	----------