

CONDITION CHECK REPORT

BH No.	400756	CHASSIS No.	RE3-1100834
--------	--------	-------------	-------------

DATE **2020 / 9 / 23**

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE		
2	COOLANT LEVEL	OK	LEAK		14	POWER WINDOW (L FRONT)	OK	NG				NONE	
3	ENGINE OIL LEVEL	OK	DIRT		15	POWER WINDOW (R REAR)	OK	NG				NONE	
4	OIL LEAKING	OK	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG				NONE	
5	TIRE (R FRONT)	OK	225/60R18	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE		
6	TIRE (L FRONT)	OK	/	R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	/	R	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	/	R	RFT	<p style="text-align: center;">(COMMENT)</p> <p style="font-size: 1.5em; text-align: center;">スリット - !</p> <p style="font-size: 1.5em; text-align: center;">パワーステアリング - !</p> <p style="font-size: 1.5em; text-align: center;">ハンドビルズ</p> <p style="font-size: 1.5em; text-align: center;">シートベルト</p> <p style="font-size: 1.5em; text-align: center;">エアバッグ</p>						TESTER CHECK	
9	ENGINE NOISE	OK	E/G	OTHERS									
10	ENGINE CONDITION	OK	IDLING	SMOKE									
11	EXHAUST LEAK	OK	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT / MT)	OK	SHOCK	NOISE	SLIP								
OPTION													
RABTD		CD		DVD		SUN ROOF		FLIP DOWN MONITOR					
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)					
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。						(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オプションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。							

YARD	ECL木更津
------	--------

INSPECTER	[Signature]
-----------	-------------

AA SHEET	9
----------	---