

# CONDITION CHECK REPORT

BF No.	BH 501 P05	CHASSIS No.	RG 1-1356532
--------	------------	-------------	--------------

DATE 2020 / 9 / 30

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG			NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG			NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG			NONE
5	TIRE (R FRONT)	OK	NG	205/60 R16		RFT	17 AIR CONDITION	OK	NG	WIND BLOWS OK		NONE
6	TIRE (L FRONT)	OK	NG	205/60 R16		RFT	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	205/60 R16		RFT	19 CHECK / WARNING LAMP	<del>OK</del>	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	205/60 R16		RFT	(COMMENT) E/G 対応 1.5L 補給 22.7L 対応 4.2L 対応 7.5L 対応					
9	ENGINE NOISE	OK	NG	E/G	OTHERS							
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP						
OPTION												
	RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR							
	REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)							
	POWER BACK DOOR											
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。					

Yard

Inspector 70

AA SHEET 0