

CONDITION CHECK REPORT

BF No.	BH514240	CHASSIS No.	WFO2972			
1	CORROSION CONDITION (Less than)	0%	25% 	50%	75%	100%
2	Holes	NO 	YES			
3	Broken	NO 	YES			
4	Engine	OK 	NG			
5	Brake System	OK 	NG			
6	Heater	OK 	NG			
7	Power Window	OK 	NG			
8	Transmission	OK 	NG			
9	A/C	OK 	NG			
10	Audio System	OK 	NG			
11	4WD Working	OK 	NG	NONE		
<p>(Comment)</p> <p>THERE IS NO GUARANTEE ABOUT HOLES AND BROKEN</p> <p>SOLD AS IS & SHOWN.</p>						
<p>UPDATE 2020/10/05 ver 1.0</p>						