

CONDITION CHECK REPORT

BF No.	BH547952	CHASSIS No.	RZH1254001839	DATE	2020 / 10 / 28
--------	----------	-------------	---------------	------	----------------

1	TIMING BELT CHANGE	YES	KM			13	POWER WINDOW (R FRONT)	OK	NG			NONE	
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG			NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG			NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG			NONE	
5	TIRE (R FRONT)	OK	NG	215/70R15	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE	
6	TIRE (L FRONT)	OK	NG	215/70R15	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	215/70R15	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	215/70R15	RFT	(COMMENT) A/C FAILURE					TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION ((AT) / MT)	OK	NG	SHOCK	NOISE						SLIP		
OPTION													
	RADIO												
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。													
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	横浜(SYNC 三井倉庫J号地)
------	------------------

INSPECTER	金岡
-----------	----

AA SHEET	✓
----------	---