

CONDITION CHECK REPORT

BF No.	BH549980	CHASSIS No.	SG5-096285	DATE	2020 / 10 / 30
--------	----------	-------------	------------	------	----------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE	
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG			NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG			NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG			NONE	
5	TIRE (R FRONT)	OK	NG	215/55R17		RFT	17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE	
6	TIRE (L FRONT)	OK	NG	215/55R17		RFT	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	215/55R17		RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	215/55R17		RFT	(COMMENT) INTERIOR STINKY (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。				TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO		C D											

YARD	大黒(SPX C-3ヤード)	INSPECTER	金岡	AA SHEET	✓
------	----------------	-----------	----	----------	---