

CONDITION CHECK REPORT

Hiace Commuter

BH No.	551115	CHASSIS No.	LH184-1002689	DATE	20/10/24
--------	--------	-------------	---------------	------	----------

1	TIMING BELT CHANGE	<input checked="" type="radio"/> NO	<input checked="" type="radio"/> YES	156604			K13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/> OK	NG			NONE	
		<input checked="" type="radio"/> OK	NG	LEAK				K14	POWER WINDOW (L FRONT)	<input checked="" type="radio"/> OK	NG			NONE
2	COOLANT LEVEL	<input checked="" type="radio"/> OK	NG					K15	POWER WINDOW (R REAR)	OK	NG		<input checked="" type="radio"/> NONE	
3	ENGINE OIL LEVEL	<input checked="" type="radio"/> OK	NG	DIRT				K16	POWER WINDOW (L REAR)	OK	NG		<input checked="" type="radio"/> NONE	
4	OIL LEAKING	<input checked="" type="radio"/> OK	NG	SMALL	BIG			K17	A/C CONDITION	<input checked="" type="radio"/> OK	NG	WIND BLOWN OK	CAN'T OPERATE	A/C NONE
5	TIRE (R FRONT)	<input checked="" type="radio"/> OK	NG	195/70 R15	R15	RFT		K18	INTERIOR CONDITION	<input checked="" type="radio"/> OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
6	TIRE (L FRONT)	<input checked="" type="radio"/> OK	NG	195/70 R15	R15	RFT		K19	CHECK / WARNING LAMP	<input checked="" type="radio"/> OK	E/G	ABS	AIRBAG	OTHER
7	TIRE (R REAR)	<input checked="" type="radio"/> OK	NG	195/70 R15	R15	RFT		(COMMENT) D3-1 や3:4 (⊕) 左STP + QT連 = 計 (⊕) 右左QT (⊕) + 7207.1 = 計 (⊕) か? / BT7 FがTR4K? 外装Tアはカシ						
8	TIRE (L REAR)	<input checked="" type="radio"/> OK	NG	195/70 R15	R15	RFT								
9	ENGINE NOISE	<input checked="" type="radio"/> OK	NG	E/G	OTHERS									
10	ENGINE CONDITION	<input checked="" type="radio"/> OK	NG	IDLING	SMOKE									
11	EXHAUST LEAK	<input checked="" type="radio"/> OK	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT/MT)	<input checked="" type="radio"/> OK	NG	SHOCK	NOISE	SLIP		TESTER CHECK						
OPTION														
<input checked="" type="radio"/> RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR										
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)										
POWER BACK DOOR														
(注意) オプションが付いているものは「○」、付いていないものは「×」、オプションが付いていないものは「無印」で表示します。							(注意) NGが入った項目は、窓ガラスに貼付せずコメントにすべて記載をお願いします。オーグメントシートをチェックして、U-83以上の窓ガラス、フロントガラスの割れやヒビ(マーカで隠して)、その他目立つ破損部分があった場合は、写真撮影をお願いします。							

YARD	野田	INSPECTER	KS	AA SHEET	0
------	----	-----------	----	----------	---