

CONDITION CHECK REPORT

353/D-4

BH No	554512	CHASSIS No.	BE437E-30583
-------	--------	-------------	--------------

DATE 2020/10/28

1	TIMING BELT CHANGE	YES				13	POWER WINDOW (R FRONT)	OK	NG			NONE		
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG			NONE		
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG			NONE		
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG			NONE		
5	TIRE (R FRONT)	OK	NG	700' - R16	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE		
6	TIRE (L FRONT)	OK	NG	700' - R16	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL		
7	TIRE (R REAR)	OK	NG	700' - R16	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER		
8	TIRE (L REAR)	OK	NG	700' - R16	RFT	(COMMENT) エイパル 下廻り、フルゲージ ショック、スパーアビ フルキー、ランプ、点検						TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS									
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE									
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE							SLIP		
OPTION														
RADIO			C/D		DVD		SUN ROOF		FLIP DOWN MONITOR					
REAR MONITOR			BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)					
POWER BACK DOOR														
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」でお願います。														
(注意) NGが入った項目は、窓ガラスに貼付せずコメントにすべて記載をお願いします。オークションシートをチェックして、U9・B9以上の傷みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。														

YARD	マツミ
------	-----

INSPECTOR	[Signature]
-----------	-------------

AA SHEET	✓
----------	---