CONDITION CHECK REPORT

BF No.	BH560693	CHASSIS No.	VY12-534107

DATE 2020 / 10 / 29

1	TIMING BELT CHANGE		YES			KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE
2	COOLANT LEVEL	OK	NG	LEAK			14	POWER WINDOW (L FRONT)	OK	NG			NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15	POWER WINDOW (R REAR)	OK	NG			NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	OK	NG			NONE
5	TIRE (R FRONT)	OK	NG	165 /	R 13	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	OK	NG	165 /	R13	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	165 /	R 13	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	165 /	R 13	RFT		(COMMENT)			TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS			○車内全体汚れ					
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP							

OPTION

RADIO	C D	DVD	SUN ROOF	FLIP DOWN MONITOR
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)
POWER BACK DOOR				

（注意） オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

（注意） NGが入った項目は、窓ガラスに記載せずコメントにすべて記載お願いします。
オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ（マーカーで囲んで）、その他目立つ破損部分があった場合は、写真撮影お願いします。

YARD	ナガセ自動車株式会社	INSPECTER		AA SHEET