

# CONDITION CHECK REPORT

BF No.	BH565767	CHASSIS No.	KSP130-2157593	DATE	2020 / 11 / 4
--------	----------	-------------	----------------	------	---------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG			NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG			NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG			NONE
5	TIRE (R FRONT)	OK	NG	165/70R14		RFT	17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE
6	TIRE (L FRONT)	OK	NG	165/70R14		RFT	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	165/70R14		RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	165/70R14		RFT	(COMMENT)				TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS							
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP						
OPTION												
RADIO		C D										
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。												
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。												

YARD	木更津・畑沢(SPX)	INSPECTER	伊藤	AA SHEET	✓
------	-------------	-----------	----	----------	---