# CONDITION CHECK REPORT

| BF No. | BH567388 | CHASSIS No. | WE5AT268362 | DATE | 2020 / 11 / 5 |
|---|---|---|---|---|---|

| | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | TIMING BELT CHANGE | | YES | KM | | | 13 | POWER WINDOW (R FRONT) | OK | NG | | | NONE |
| 2 | COOLANT LEVEL | OK | NG | LEAK | | | 14 | POWER WINDOW (L FRONT) | OK | NG | | | NONE |
| 3 | ENGINE OIL LEVEL | OK | NG | DIRT | | | 15 | POWER WINDOW (R REAR) | OK | NG | | | NONE |
| 4 | OIL LEAKING | OK | NG | SMALL | BIG | | 16 | POWER WINDOW (L REAR) | OK | NG | | | NONE |
| 5 | TIRE (R FRONT) | OK | NG | 7.00/ R15 | | RFT | 17 | A/C CONDITION | OK | NG | WIND BLOWS OK | CAN'T OPERATE | NONE |
| 6 | TIRE (L FRONT) | OK | NG | 7.00/ R15 | | RFT | 18 | INTERIOR CONDITION | OK | NG | DIRT | SMOKING SMELL | OTHER SMELL |
| 7 | TIRE (R REAR) | OK | NG | 7.00/ R15 | | RFT | 19 | CHECK / WARNING LAMP | OK | E/G | ABS | AIRBAG | OTHER |
| 8 | TIRE (L REAR) | OK | NG | 7.00/ R15 | | RFT | | | | | TESTER CHECK | | |
| 9 | ENGINE NOISE | OK | NG | E/G | OTHERS | | | | | | | | |
| 10 | ENGINE CONDITION | OK | NG | IDLING | SMOKE | | | | | | | | |
| 11 | EXHAUST LEAK | OK | NG | MUFFLER RUSTY | MISSING PARTS | | | | | | | | |
| 12 | TRANSMISSION ( AT / MT ) | OK | NG | SHOCK | NOISE | SLIP | | | | | | | |

(COMMENT)

A/C NONE
RADIO FAILURE

| OPTION | | | | |
|---|---|---|---|---|
| ~~RABIO~~ | | | | |
| | | | | |
| | | | | |

(注意) オプション品が付いていて作動するものは「○」、 付いていて作動しないものは「×」、
オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載お願いします。
オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影お願いします。

| YARD | 神戸(サンフェニックスRS-B) | INSPECTER | 岡 | AA SHEET | ✓ |
|---|---|---|---|---|---|