

CONDITION CHECK REPORT

| | | | |
|--------|--------|-------------|--------------|
| BH No. | 574353 | CHASSIS No. | HA24S-658054 |
|--------|--------|-------------|--------------|

DATE **2020 / 11 / 5**

| | | | | | | | | | | | | | | |
|---|------------------------|-------------|-----|----------------|---------------|---------------------------|---|----------------------------|-----|---------------|---------------|-------------|--------------|--|
| 1 | TIMING BELT CHANGE | | YES | | KM | 13 | POWER WINDOW (R FRONT) | OK | NG | | | | NONE | |
| 2 | COOLANT LEVEL | OK | NG | LEAK | | | POWER WINDOW (L FRONT) | OK | NG | | | | NONE | |
| 3 | ENGINE OIL LEVEL | OK | NG | DIRT | | | POWER WINDOW (R REAR) | OK | NG | | | | NONE | |
| 4 | OIL LEAKING | OK | NG | SMALL | BIG | | POWER WINDOW (L REAR) | OK | NG | | | | NONE | |
| 5 | TIRE (R FRONT) | OK | NG | 13.5 80 R12 | | RFT | A/C CONDITION | OK | NG | WIND BLOWS OK | CAN'T OPERATE | A/C NONE | | |
| 6 | TIRE (L FRONT) | OK | NG | | R | RFT | INTERIOR CONDITION | OK | NG | DIRTY | SMOKING SMELL | OTHER SMELL | | |
| 7 | TIRE (R REAR) | OK | NG | | R | RFT | CHECK / WARNING LAMP | OK | E/G | ABS | AIRBAG | OTHER | | |
| 8 | TIRE (L REAR) | OK | NG | | R | RFT | (COMMENT) <div style="font-size: 1.5em; text-align: center;">リモコン</div> <div style="font-size: 1.5em; text-align: center;">車内汚れ.</div> | | | | | | TESTER CHECK | |
| 9 | ENGINE NOISE | OK | NG | E/G | OTHERS | | | | | | | | | |
| 10 | ENGINE CONDITION | OK | NG | IDLING | SMOKE | | | | | | | | | |
| 11 | EXHAUST LEAK | OK | NG | MUFFLER RUSTY | MISSING PARTS | | | | | | | | | |
| 12 | TRANSMISSION (AT / MT) | OK | NG | SHOCK | NOISE | SLIP | | | | | | | | |
| OPTION | | | | | | | | | | | | | | |
| RADIO | | CD | | DVD | | SUN ROOF | | FLIP DOWN MONITOR | | | | | | |
| REAR MONITOR | | BACK CAMERA | | CRUISE CONTROL | | POWER SLIDING DOOR (LEFT) | | POWER SLIDING DOOR (RIGHT) | | | | | | |
| POWER BACK DOOR | | | | | | | | | | | | | | |
| (注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。 | | | | | | | (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。 | | | | | | | |

| | |
|------|--------|
| YARD | ECL木更津 |
|------|--------|

| | |
|-----------|-----|
| INSPECTER | イズミ |
|-----------|-----|

| | |
|----------|---|
| AA SHEET | 0 |
|----------|---|