

CONDITION CHECK REPORT

BF No.	BH577681	CHASSIS No.	MA15S-130651
--------	-----------------	-------------	---------------------

DATE 2020 / 11 / 7

No.	Item	Status	Leak	Oil	Tire	Engine	Transmission	Power Window	A/C	Interior	Warning	Other
1	TIMING BELT CHANGE		YES									NONE
2	COOLANT LEVEL	OK	NG	LEAK								NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT								NONE
4	OIL LEAKING	OK	NG	SMALL	BIG							NONE
5	TIRE (R FRONT)	OK	NG	165/65R 14	RFT							NONE
6	TIRE (L FRONT)	OK	NG	165/65R 14	RFT							NONE
7	TIRE (R REAR)	OK	NG	165/65R 14	RFT							NONE
8	TIRE (L REAR)	OK	NG	165/65R 14	RFT							NONE
9	ENGINE NOISE	OK	NG	E/G	OTHERS							NONE
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							NONE
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							NONE
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK	NOISE	SLIP						NONE
OPTION												
RADIO		CD		DVD		SUN ROOF		FLIP DOWN MONITOR				
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)				
POWER BACK DOOR												
<p>(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。</p>												
<p>(COMMENT)</p> <p style="font-size: 1.2em;">F. バンパーに引すりかたあり シートスリコケあり、ヨゴレ 室内ヨゴレ スパアタケル車 バックドア開きが悪い (引つかり有) 天張りヨゴレ小</p>												
<p>(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ（マーカで囲んで）、その他目立つ破損部分があった場合は、写真撮影をお願いします。</p>												

YARD	ナガセ自動車株式会社
------	------------

INSPECTER	尾銅 寛也
-----------	-------

AA SHEET
