

CONDITION CHECK REPORT

BH No 583382

CHASSIS No

WDC2030462R208647

DATE 2020/11/20

1	TIMING BELT CHANGE	YES																	
2	COOLANT LEVEL	OK	NG	LEAK					13	POWER WINDOW (R FRONT)	OK	NG							NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT					14	POWER WINDOW (L FRONT)	OK	NG							NONE
4	OIL LEAKING	OK	NG	SMALL E/G					15	POWER WINDOW (R REAR)	OK	NG							NONE
5	TIRE (R FRONT)	OK	NG	225/45 R 17	RFT				16	POWER WINDOW (L REAR)	OK	NG							NONE
6	TIRE (L FRONT)	OK	NG		R	RFT			17	AIR CONDITION	OK	NG	WIND SLOWS OK						NONE
7	TIRE (R REAR)	OK	NG	245/40 R 17	R	RFT			18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL				
8	TIRE (L REAR)	OK	NG		R	RFT			19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER				
9	ENGINE NOISE	OK	NG	E/G	OTHERS				(COMMENT) ・ハンドル、スレ ・ダッシュボードのり ・左右ドアミラー - ウィンカー切れ (ウィンカー早い)										
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE														
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS														
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK	NOISE	SLIP													
		OPTION																	
RADIO		OD		DVD		SUN ROOF		FLIP DOWN MONITOR											
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)											
POWER BACK DOOR																			
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いたします。										(注意) NGが入った項目は、居ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、US/E3以上の出力キス、フロントガラスの割れやコド(マーカで歪んで)、その他目立つ瑕疵部分があった場合は、写真撮影をお願いします。									

Yard

ECL新門司

Inspector

KK2

AA SHEET

