

CONDITION CHECK REPORT

BF No.	BH587472	CHASSIS No.	SK82T-400772
--------	----------	-------------	--------------

DATE 2020 / 11 / 12

1	TIMING BELT CHANGE		YES		122885	KM		13	POWER WINDOW (R FRONT)	OK	NG			NONE
2	COOLANT LEVEL	OK	NG	LEAK				14	POWER WINDOW (L FRONT)	OK	NG			NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT				15	POWER WINDOW (R REAR)	OK	NG			NONE
4	OIL LEAKING	OK	NG	SMALL	BIG			16	POWER WINDOW (L REAR)	OK	NG			NONE
5	TIRE (R FRONT)	OK	NG	165 /	R 14	RFT		17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	OK	NG	165 /	R 14	RFT		18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	145 /	R 12	RFT		19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	145 /	R 12	RFT		(COMMENT) シートカブレヨコレ 天張りヨコレ タッチホードのりあり 空力. 天張りヨコレ					TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS									
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE									
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK	NOISE	SLIP								
OPTION														
RADIO	C D	DVD	SUN ROOF	FLIP DOWN MONITOR										
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)										
POWER BACK DOOR														
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。														
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ（マーカで囲んで）、その他目立つ破損部分があった場合は、写真撮影をお願いします。														

YARD	ナガセ自動車株式会社
------	------------

INSPECTER	尾崎竜也
-----------	------

AA SHEET
