

SPECS

| | | | |
|-------------------|----------|------------------|----------------------|
| Ref No | BH590130 | Location Country | United Kingdom |
| Chassis # | JD1017 | Ver/Class | MANUAL DIESEL |
| Model Code | | Ext.Color | Green |
| Engine Size | 0 cc | Fuel | Diesel |
| Drive | 4WD | Seats | 1 |
| Transmission | Manual | Doors | 2 |
| Mileage | 0 mile | Weight | |
| Engine Code | | Dimension | 4.80 × 2.50 × 3.20 m |
| Steering | Center | M3 | 38.400 |
| Registration Year | 2014 | | |
| Manufacture Year | | | |

STANDARD FEATURES

| | | | |
|----------------|-----------------|-------------------|--------------|
| CD Player | Sun Roof | Leather Seat | Alloy Wheels |
| Power Steering | Power Window | A/C | ABS |
| Airbag | Radio | CD Changer | DVD |
| TV | Power Seat | Back Tire | Grill Guard |
| Rear Spoiler | Central Locking | Jack | Spare Tire |
| Wheel Spanner | Fog Lights | Back Camera | Push Start |
| Keyless Entry | ESC | 360 Degree Camera | |
| | | | |

SUPPLIER'S CONDITION REPORT

| | | | |
|-------------------|---------|-----|------|
| Corrosion | NO | YES | |
| Under Body Holes | NO | YES | |
| Under Body Broken | NO | YES | |
| Engine | Working | NG | |
| Brake System | Working | NG | |
| Heater | Working | NG | |
| Power Window | Working | NG | |
| Transmission | Working | NG | |
| A/C | Working | NG | |
| Audio System | Working | NG | |
| 4WD | Working | NG | NONE |

COMMENTS

THERE IS NO GUARANTEE ABOUT HOLES AND BROKEN

SOLD AS IS & SHOWN

DATE 2020/11/12