

CONDITION CHECK REPORT

BF No.	BH589749	CHASSIS No.	GE6-1371310
--------	----------	-------------	-------------

DATE 2020 / 11 / 13

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE	
2	COOLANT LEVEL	OK	NG	LEAK			14	OK	NG			NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT			15	OK	NG			NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG		16	OK	NG			NONE	
5	TIRE (R FRONT)	OK	NG	175/65 R 14		RFT	17	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	OK	NG	175/65 R 14		RFT	18	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	175/65 R 14		RFT	19	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	175/65 R 14		RFT	(COMMENT) ホンダ不良 (AVに入らない) 化けOK 画面音不良 室内ヨゴシ フロアマットスリ穴 ミットス パンク修理モト. IR-ポンプなし スリ3ヶ所 車						
9	ENGINE NOISE	OK	NG	E/G	OTHERS							TESTER CHECK	
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO	CA	DVD	SUN ROOF	FLIP DOWN MONITOR									
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。													
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ（マーカーで囲んで）、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	ナガセ自動車株式会社
------	------------

INSPECTER	尾崎 敏也
-----------	-------

AA SHEET
